Service No. 47 Name Mary Videtta Address 109 Bow Street Location Lexington, Mass. 109 Bow Street Kind of Pipe Size of Main Size Repair & Remark New Service Location Com. 10-10-49 **Amount** Material Total Date Amount. Date 06 lys 8 49 8000 Aug. 30. 49 Labor 31 06 10% Overhead 11 28' - 6" Sewer Pipe @. 265 42 5.55 ------- $1 - 6^{\text{H}}$  Elbow 52 1 68 Joint Compound Littlefield Shovel 2 hrs.@7 00 17 50 Trucking 2 hrs. @ 75 1 50 63 79 Labor TP-7019

## TOWN OF LEXINGTON-DEPT. OF PUBLIC WORKS

## SEWER DIVISION

Am't of estimate	m't of estimate \$																											
Am't Paid \$																												
	·																	• • •	•••								 . Ov	/ner
				Sketch of Service Here																				 				
			1						T	I			I		I	I	I		1	J		1	I		I	<u>.</u>		
	_	1	1	1 1	-   -	_	_		1		<u> </u>			1	-	1	<u> </u>	<u> </u>		-}-			4	1-1		-		
	-	1 1		1 +		+			-+	+-	+		+-	-	-	+	+-			-}-		+			-	•		
•		++		+-+	+	+	+-		-+	+	+-1		+	+-	$\dashv$	+	+-		+	+	+-1	-+	+	+-		-		
	<del></del>	11	1	11	++	1			1	十			+	1	+	十	丁		1	1	11	寸	1	11	1	•	•	
									1				Ī			I				I		Ì				•		-
		1 1			11	1							-			1	1			Ţ			Ļ		1	-		
		<del>                                     </del>		<del>]                                    </del>	<del>- }- }</del>				-+	<del> </del>	-		1	<u> </u>		+	4-				1	_		<u> </u>		-		
		11	-	<del>}                                    </del>	-{-;		-			+	+	<u>                                     </u>		-		-}-	<del></del>			+					-	-		
		++			_{	+	+			+	╁═		+	+-	$=\downarrow$	+	<del></del>		+	-+-	+-	+	+	<del></del>		-		