

三

Address 15 Wheeler Rd

Service No. 2391

Location \_\_\_\_\_ Lot 126

### **Kind of Pipe PVC + clay**

Repair—General—New Service

१०

6

**Repair—Removal—New Service** *J. McLaughlin*

Location

**Amount**      **Date**  
**Material**      **Total**

4307	6'	4"	PVC sch 40
49	6'	PVC	sch 35
1	4"X6"	Ferco	
1	6"	Clayx PVC	Ferco
1954	6"	Clay Pipe - ST.	

Connection made in ..... Street ..... Work completed ..... Remarks:

A black and white photograph showing a dense grid pattern of horizontal and vertical lines, likely representing a wire mesh or a metal grate. The grid is composed of thin, dark lines forming a series of small, equal-sized rectangles across the entire frame.

Schedule of Service Hours

## **SEWER DIVISION**

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

-31-