

WATER SERVICE RECORD

Name Don Irwin

Service No. 26

Address 51 North St.

*Corner is East St. Batten  
Irwin is 2nd*

Location

~~REPAIR WORK~~ - New Service

*Com. 3-15-54*

Date	Material	Amount	Total	Date	Amount
2/26/54	Labor	14 25		2-18-54	Deposited 175 00
	10% overhead	1 43	15 68	3-15-54	Refunded (27 43)
	170' -1" copper tubing @.4502		76 53		<u>NON CHARGE</u> 147 57
	1 -1"C x 3/4" I.W.H. stop & waste	4 50		2/26/54	Labor 14 25
	2 - 1"C x 1"C. unions @2.26	4 52			30' - 1" copper tubing@.4502 13 51
	1 -1" x 3/4". Red.bushing		59		1 -1"C. corp-cock 5 61
	4 hrs. Littlefield shovel@ 7.50	30 00			1 - 1"C x 1"C.curb cock 6 80
	1 hr. trucking		75		1 box and rod 3 90
	patching 15 x 3		15 00		1 - $\frac{1}{2}$ offset tail pc. 50
			147 57		1 - $\frac{1}{2}$ straight tail pc. 50
					2 hrs. Littlefield shovel@ 7.50 15 00
					1 hr. trucking 75
					<u>60 82</u>

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 25 rows high, intended for sketching service details.

Connection made in ..... Street.      Work completed .....

Remarks: .....

.....

.....