

Name Site & Shelter

Service No. 232

Address 524 Concord Avenue

#2067

Location

Kind of Pipe

Size

Size of Main

~~Repair-Renewal~~—New Service

Com. 12-5-51

Location

Date	Material	Amount	Total	Date	Amount
11-7-51	Labor	1 49	1 49	<i>9-25-51</i>	<i>Deposited</i> 10 00
	10% Overhead		15	<i>9-8-52</i>	<i>Paid</i> 23 97
	18'-3/4" Copper Tubing @.326		5 86	<i>9-28-52</i>	<i>Paid</i> 33 97
	1-3/4"Cx1/2 I.W.H S&W		4 00		<i>No Charge</i> 23 97
	1-3/4"Cx3/4"C Union (3 pts)		1 72	11-7-51	Labor 9 01
	1 Hr.Trucking		75	28'- 3/4" Copper Tubing @.326	9 12
	Patching 20x3		20 00	1-3/4"C Corp Cock	4 33
	Total		33 97	1-3/4"Cx3/4"C Curb Cock	4 67
	Trench Dug By Owner			1-Box & Rod	4 68
	Pipe Supplied And Laid By Owner			1-1/2 Offset Tail Piece	50
	Labor			1-1/2 Straight Tail Piece	50
				4 Hr Littlefield Shovel @ 7.00	28 00
				1 Hr. Trucking	75
				Total	61 56

The Daily Press, Boston

6-15-51
2-15-52

