

Name Robert Esty
 Address 17 Henderson Road
 Lexington

Service No. 146 2567

Location 17 Henderson Road

Kind of Pipe Size Size of Main
~~Repair-Replace~~ - New Service Com. 9-5-50 Location

Date	Material	Amount	Total	Date	Amount
July 11 '50	Labor	4 35		June 26 '50	80 00
	10% Overhead	44	4 79	Reported	
	64' - 3/4" Copper Tubing @ 23¢	14 72			
	1 - 3/4"C x 1/2" I.W.H. S&W	3 29		No Charge	
	1 - 3/4"C x 3/4"C Union (3pts)	1 39		July 11 '50	3 00
	4 hrs. Littlefield Shovel	28 00		Labor	
	1 hr. Trucking		75	12' - 3/4" Copper Tubing @ 23¢	2 76
	Patching 6 x 3		6 00	1 - 3/4"C. Corp-cock	3 15
			58 94	1 - 3/4"C x 3/4"C Curb-cock	3 85
				1 Box & Rod	3 35
				1 - 1/2" Offset Tail Piece	38
				1 - 1/2" Straight Tail Piece	38
				1 hr. Littlefield Shovel	7 00
	Labor			1 hr. Trucking	75
					24 62

