

WATER SERVICE RECORD

Name Benjamin Franklin Homes, Inc.

Service No. 358

Address 34 Peacock Farm Road

Location

~~Repair - Renewal~~ - New Service

SERVICE WAS IN TO CURB

Date	Material	Amount	Total	Date	Amount	
11/21/56	Labor	1 95		11-19-56	Deposit	\$ 40 00
	10% overhead	20	2 15	12-31-56	Paid by Refunder ^{r. H.C.} \$32	14 75
	92' - 3/4" Copper tubing @ .4850		44 62		NON CHARGE	\$ 54 75
	1 - 3/4" Cx 1/2 I.W.H. Stop & Waste		4 96		1 - 1/2 Straight tailpiece	50
	1 - 3/4 Union (3 part)		2 27		1 - 1/2 Offset tailpiece	50
	1 hr. trucking		75			1 00
			54 75			

