

Name Edson V. Sears

Service No.

Address 10 Berwick Road

Lexington, Mass.

Location 10 Berwick Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Com. 8-16-48

Location

Date	Material	Amount	Total	Date	Amount
July 20, '48	Labor	17 00		June 24 '48	125 00
21		38 93		Aug 20 '48	42 96
22		19 83	75 76		122 04
	10% Overhead		7 58		
	60' - 6" Sewer Pipe @ .26		15 60		
	1 - 6" 1/4 Bend		1 50		
	Joint Compound		3 60		
	Littlefield Shovel 1 1/2 hrs. @ 7.00		10 50		
	Trucking 2 hrs. @ .75		1 50		
	Patching 16 x 3		16 00		
			122 04		
	Labor				

