Name Bicentennial Builders Corp.					Service No.			
Add		+180 EASTEMER		(LOT#	40)			
					Location			
Kind of Pipe PVC				Size 6"		Size of Main 8"PVC		
Repair Ranewel New Service Eagle #4170				Location				
Date		Material	Amount	Total	Date		Amount	
5/20/83	168	x 6" P.V.C.						
	10	x 4" C.I.P.						
	1	Precast Manhole w/l	Frame & cover					
	100	Red Sewer Brick				OUTSIDE		
						Installed By Contractor		
	ļ							
	ļ							
		_	1					
	<u> </u>		1		<u> </u>			
	ļ							
					#			
			1 1	!) <u> </u>	1	i	