

Name

Service No. 1432

Address 506 Dunthrop RD

Location

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service

Location

Date	Material	Amount	Total	Date	Amount
6/10/04	3.0 6" PVC stub				
	4 6' 6" PVC				
	5.6" 4" PVC sch 40				
	1 4" x 6" Furanco				
	1-6" 1 1/4" bend				
	1 6" x 6" PVC Furanco				
	EXISTING A.C.				
7/19/02	1 90° Elbow				

