



Address	Map and Lot	Permit Number	Contractor Name	Inspector
149 Adams St	75-26	6151	McLaughlin, James M. Inc.	dpavlik msprague
Date	Material	Depth of Cover	Amount	
5/7/2015	6x6 Fern Co	12 ft	1-Connect to existing stub	
	6" PVC Pipe - SDR 35		135 ft to 22° Bend	
	22° Bend		1	
	6" PVC Pipe - SDR 35		39.6 ft to 45° Bend	
	45° Bend		2.2 ft to Clean out	
	PVC Clean Out		1	
	45° Bend		3 ft to Fernco	
Type of work completed				

New 6" PVC sewer service installed to new house, connection to existing stub at main.