									7.00	
Name	Joseph A. Veneda	m						Service No.	192	
Address	62 Adams Street			· 						
					Loca	ation				
Kind of Pipe			Size				Size of Main			
Repair	Renewal—New Service	. COM.	11-	<u>30-53</u>				Location	 	
Date	Material	Amount		Total		Date			Amou	unt
11/10/53	Labor	38	17			10-29	ुं े	Depositod	150	00
	10% Overhead	3	82	41	99	11-30			(18	0/
	66' - 6" sewer pi	pe <u>303</u> 6	5 _	20	04_				131	99
<u></u>	joint compound			3	96					
	7 hrs. Littlefiel	ā shove.	<u>@</u> 7.	50 52	50					
	2 hrs. trucking			1	50	* 4	y , 3, 4	5 of this	1/2 40	
	patching 12 x 3			12		ma	No	manoble de	Tone	
				131	99	La	9,0	an but	No.	
						es	11	n. N. C. # 35	4	
					· ·			W.11. C 55		
	Labor	<u> </u>								<u> </u>
						 				· · · · · · · · · · · · · · · · · · ·
	<u> </u>	<u> </u>								
HP-7919								<u> </u>	<u> </u>	
) HP-7919	1	ļ	•	•		"		•		

TOWN OF LEXINGTON—DEPT. OF PUBLIC WORKS

SEWER DIVISION

DATE										
Sewers, as now or at any future time established by the Board of Selectmen.										
Am't of estimate \$										
Am't Paid \$										
			Owner							
	SI	ketch of Service Here								
			<u> </u>							
	 	<u> </u>	<u> </u>							
		 	<u> </u>							
			† † 							
			 							
										
			† †							
	<u> </u>		<u> </u>							
Connection mad	in	Street. Work completed	19							