

Name **Alvar V. Melin**

Service No. **159**

Address **81 Adams Street**

Location

Kind of Pipe

Size

Size of Main

~~Repair/Renewal~~ **New Service**

COM. 10-31-55

Location

Date	Material	Amount	Total	Date	Amount
9/22/55	Labor	87 98		8-9-55	Deposited 130 00
	10% overhead	8 80	96 78	11-1-55	Refunded (7 00
	44' - 6" sewer pipe @ .32		14 08		123 00
	Joint compound		2 64		
	1 - 6x6 Y		1 62		
	1 - 6" elbow		1 88		
	6x3 patching		6 00		
			<u>123 00</u>		
	Labor				

