

Name Benjamin Franklin Homes, Inc.

Service No. #82

Address 10 Angier Road

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~XXXXXXXXXXXX~~ New Service

WO #7363

Location


Cum 10-1-62

Date	Material	Amount	Total	Date		Amount
7-13-62	Labor	78.14		6-18-62	Deposit	175.00
	10% O.H.	7.81	85.95	10-1-62	Paid by SHC #56	<u>25.02</u>
	147' 6" Transite Pipe @.78		114.66			<u>220.02</u>
	1 22½° Transite Bend		4.09			
	2 11¼° Transite Elbow @2.45		4.70			
	1 6" Transite Adapter		1.62			
	3 Hrs. Trucking @3.00		9.00			
			220.02			
	OWNER DUG TRENCH					

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here

A large rectangular area filled with a grid of small squares, intended for drawing a sketch of sewer service details.

Connection made in Street. Work completed

Remarks:
.....
.....