Name Address	Antonio Busa 1 Anthony Road		62-8 404 Werling 52- Willed Location Con	Wis Werling Wis West	Service No. 21
Kind of Pipe	Pipe		Size		Size of Main
Mepaire	Repaire Repewak-New Service				Location
Date	Material	Amount	Total	Date	
10/26/56 Labor	bor	17 40		2	b desposit
10	10% overhead	1 74	19 14	4-1-67	Paid Ly refund
361	- 6" Sewer pipe	© •435	15 66		on W. H.C. #324 #
Joi	Joint compound		2.16		
2 1	hrs. Trucking @ .75	O C	1 50		
			38 46		
	Labor			5/10/13	20/1/5
					201

## TOWN OF LEXINGTON-DEPT. OF PUBLIC WORKS

## SEWER DIVISION

Sewers, as now or at any future time established by the Board of Selectmen.	Street and hereby agrees to comply with the Rules and Regulations governing the construction and use of Particul	The undersigned applies for the construction of a particular sewer connecting No	DATE
	tion a	:	
	and u		
	use		S
	of F	:	
	articul		NO

Am't Paid \$.....

Sketch of Service Here

..... Own

		1	1	1	1			1	1		1
_											
_					1	-					
									-		
	-		-			_	_	_		_	_
		_	_			-	_		_	_	
_	_	_	-	_		-	-	_	_	_	_
_	_	_	-	_	_	_	_	_	_	_	_
_	_	_	_	_	_	_	_	_	_	_	
		_		_	_						
	-	-	- 1			_		_			
	_		_			_		_			
									_		
			100								
			8.3								30000
	_				_					3 %	_
		_	_	_	_		_		_		_
			_	_	_	_	_				
		_	_	_	_	-	_	_	_	_	_
	_	_		_		_	_	_	_	_	
	_					-	_		-		—
	_	_	_	_	_	_	_		_	6	_
-	_	_	-	_	_	_	_	-	_		
_	_	_	_		_	_		_	_		
	_	_	_		_	_		_			
		_	_	_	_	_					