

Name William Sullivan

Service No.

Address 3 Augustus Road

Location

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service Sibley #542

Location

Date

Material

Amount

Total

Date

Amount

2/15/67 68' 6" Transite pipe

