

Name John McKenna

Service No. 77-1950

Address 81 Baker Avenue,
Lexington, Mass

Location 81 Baker Avenue

Kind of Pipe COM. 9-5-51

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Location

Date	Material	Amount	Total	Date	Amount
10/16/50	labor	65 43	65 43	9-8-50	Deposited \$100 00
	10% overhead		6 54		
	46' -6" sewer pipe		12 88		
	joint compound		2 76		
	1 hr. Littlefield shovel		7 00		
	2 hrs. trucking @ .75		1 50		
			96 11		
	NON CHARGE				
12-18-59	Labor	72 80			
	10% O. H.	7 28	80 08		
13'	6" Transite pipe @.78		10 14		
2	6" Adapters @.1.90		3 80		
4'	labor patch		4 00		
1	Hr. Town Shovel @6.50		6 50		
2	Hrs. Trucking @.75		1 50		
			106 02		

