

Name Richard Magnanti

Service No. 95

Address 15 Baskin Road

Location

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service

Location Comm 11-24-58

Date	Material	Amount	Total	Date	Amount
6/2/58	Labor	16 50		5-28-58	150 00
	10% overhead	1 65	18 15	11-24-58	96 60
	42' - 6" Transite pipe @ .70		29 40		53 40
	1 - 11 1/4" Transite bend		5 10		
	1 hr. trucking		75		
			53 40		
				7-12-92	Beick + Grease in main 4' from M.H
	Labor				

