Name	Frank E. Dea					_		Service No.	. 209				
Address	22 Baskin Road												
		_				Location	(Jamm. 2/16/0	59				
Kind of I	Pipe .		-	Size				Size of Main					
- RepairI	Renewal—New Service							Location					
Date	Material	Amour	nt	Total		Date		_	Amount				
11/25/58 L	bor	32	18			11/12/	58	Deposit	150	ao			
10	% overhead	3	22	35	40	2/16/6	59	Refund		00			
501	' - 6" Transite Pi	pe @ .70		35	00		,	0	# 90	ao			
1 -	$11\frac{1}{4}^{0}$ Transite Be	nd		5	10								
2 h	rs. Town Shovel 3	6.50		13	00					·			
2 1	rs. Trucking © .7	5		1	50				ļ				
				-90	00					<u>-</u>			
					-					L			
									ļ				
		,			-								
				ļ	:								
	Labor							· · · · · · · · · · · · · · · · · · ·	 				
		*		#					ļ <u> </u>				
										<u> </u>			
·		<u> </u>							ļ				
н.в.к.18501				 									

TOWN OF LEXINGTON—DEPT. OF PUBLIC WORKS SEWER DIVISION

The unders Street and hereb Sewers, as now Am't of estimat Am't Paid \$	y ag or a e \$	gree t a	es ny	to d	con tur	nply e ti	/ w	vith	n t	he	Rι	ules	a	nd	Re	gul	atio	ns	go elec	veri	ning en.	g t	he	cc	ns	truc	tio	n a	and	d u		Par	ticul
				_ -		===		_				Sk	etc	h	of	Ser	vic	. H	ere						=			_	-				==
	П	<u> </u>	Т	\neg	$\overline{\top}$	1	1	<u> </u>	1	Т		Τ	Τ.	T				Т	T	П	- T	Т	ī	T		_		П	$\overline{}$	$\overline{}$			
					Ì			Ė	İ	İ	Ĺ							İ	İ	İ	į	İ	İ		Ī	Ì	i		ij	\exists			
			ļ_	_ļ_	_ _	\perp		1_						<u> </u>	Ĺ				<u> </u>						Ц.	Ļ				\Box			
		_		_	+	-	<u> </u>	+	_	_	<u> </u>	╀-	<u> </u>	1_	_	<u> </u>	_	+	<u> </u>		_	_	+	+	_	 	<u> </u>		_	_			
			-	+		╬	<u> </u>	+	╁	┿	十	╀	ļ	\vdash	<u> </u>		_	+	+-		-	<u> </u>	$\frac{1}{1}$	+	+	+-		_]	4				
		\dashv		÷	-	╁	╁	十	+	╁	+	$^{\perp}$	十	<u> </u> 	<u> </u>	<u> </u>	+	+-	╁			+	-	-	$^+$	╁	ļ -		1	\neg			
		\dashv	- †	1	+	+	†	+-	+	+	+	十	十	+-	1		\dashv	 	Ť		1	\dagger	+	+	Ť	†-		1	1	7			
					\top		Ť		T	Ť	T	Ť	İ	T			1	T	Ť			\top	Ť		Ť	Ť.	Ħ		ij	T			
		\Box							\prod													\prod							[\Box			
							1_	_	<u> </u>						Į		_	1	ļ	1 1		1	1		\perp	<u> </u>	<u> </u>	Į	[_			