

Name Frank Dea

Service No. 103

Address 24 Baskin Road

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renew~~ New Service

Location

Comm 11-9-59

Date	Material	Amount	Total	Date	Amount
7-21-59	Labor 70.71			7-3-59	135.50
7-22-59	" 25.62	96.33		11-9-59	28.45
	10% O.H. 9.63		105.96	11-6-60	48.23
	80' 6" Transite pipe @.70		56.00		201.68
	6 3/4ton 1 1/4" Stone @1.50		10.13		
	1 1 1/2" Transite Bend		5.10		
	1 1 1/2" Transite Elbow		2.24		
	4 hrs. Pippin Shovel @4.50		18.00		
	3 hrs. Trucking @.75		2.25		
	2 hrs. Pump @1.00		2.00		
			201.68		

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**  
**SEWER DIVISION**

Sketch of Service Here

A large grid for sketching service details, consisting of 20 columns and 20 rows of small squares.

Connection made in ..... Street. Work completed .....

Remarks: .....

.....

.....