

Name A. J. Comeau Const.

Service No. 75.35

Address 51 Baskin Road

Location Lot #84 Sta 30.30

Kind of Pipe

Size

Size of Main

~~REPAIR EXIST~~ - New Service WO # 7304

Location Comm 7-16-62

| Date | Material | Amount | Total | Date | Amount |
|---------|--------------------------------|--------|--------|---------|----------------------|
| 7/26/61 | Labor | 38 64 | | 5-22-62 | Deposit 100 00 |
| | 10% O.H. | 3 86 | 42 50 | 7-16-62 | Paid by WH # 61 4 05 |
| | 140' 6" Transite Pipe @ .78 | | 31 20 | 4-23-62 | |
| | 1 11 1/2° Transite Bend | | 5 10 | | 175 35 |
| | 1 Hr. Trucking @ 3.00 | | 3 00 | | |
| | BILL WHEN CONNECTED | | 81 80 | | |
| 5/29/62 | Labor | 31 92 | | | |
| | 10% O.H. | 3 19 | 35 11 | | |
| | 58' 6" Transite Pipe @ .78 | | 45 24 | | |
| | 2 11 1/2° Transite Bend @ 5.10 | | 10 20 | | |
| | 1 Hr. Trucking @ 3.00 | | 3 00 | | |
| | | | 175 35 | 6/8/62 | broken meter |

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here

| | | | | | | | | | | | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | |

Connection made in Street. Work completed

Remarks:
.....
.....

