

Name Tricorn Homes Inc.

Service No. #69

Address 66 Baskin Road

Lot #50

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~XXXXXXXXXX~~ New Service WO #7338

Location *Summit-1-62*


Date	Material	Amount	Total	Date	Amount
6-15-62	Labor	21.97		6-4-62	150.00
	10% O.H.	2.20	24.17	11-1-62	59.58
	72' 6" Transite pipe @.78		56.16		90.42
	1 22 1/2" Transite Bend		4.09		
	2 Hrs. Trucking @3.00		6.00		
			90.42		
	OWNER DUG TRENCH				
6-16-	70 Repair				
	13' 6" Transite				
	1 Adapter				
				6-16-70	S.B. (Rocks)

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:
.....
.....