

Name Salvatore Casella

Service No. 146

Address 104 Bedford Street

Location

Kind of Pipe

Size

Size of Main

~~Repair~~—Renewal—~~New Service~~

W.O. # 9216

Location

APR 20 1971

Date	Material	Amount	Total	Date	Amount
12/2/70	Labor		41 88	1/30-70	200 00
	10% O.H.		4 19	4-20-71	97 23
21'	6" Transite pipe .90		18 90		102 07
1	1 1/2 Elbow		3 95	12/1/70	36 44
1	Gasket		2 65	12/2/70	36 56
3	Yds. Loam 3.50		10 50	20'	18 00
10	Lbs. Seed 1.10		11 00	1	5 65
1 1/2	Hrs. Loader 4.00		6 00	1/2	95
1	Hr. Trucking		3 00	2	12 00
			102 07	3	9 00
				1/2	75
				2	8 00
				1/2	2 00
				1/2	2 00
				1/3	1 00
					2 00
					134 35

