

Name Bowser Trust (Robert L. Tillinghast)

Service No.

Address 183 Bedford St. Lexington, Mass.

Location

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service Valeri Const. #2628

Location

Date	Material	Amount	Total	Date	Amount
------	----------	--------	-------	------	--------

5/1/75	117' 6" Transite Pipe				
--------	-----------------------	--	--	--	--

	39' 4" Cast Iron Pipe				
--	-----------------------	--	--	--	--

