

Name Mrs. Wm. D. Hagerty

Service No. 78

Address 301 Bedford Street

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

COM. 11-9-53

Location

Date	Material	Amount	Total	Date	Amount
Sept. /29/53	Labor	54 17		5-1-53	200 00
3/30/53	"	29 17		11-9-53	(7 56)
10/1/53	"	29 17	112 51		192 44
	10% overhead		11 25		
	50' -6" sewer pipe @ .3036		15 18		
	joint compound		3 00		
	5 hrs. Littlefield shovel @ 7.50		37 50		
	4 hrs. trucking @ .75		3 00		
	patching 10 x 3		10 00		
			192 44		
	Labor				

