

Name Custance Bros.

Service No. 183

Address 33 Bedford St.

Lexington

Location

Kind of Pipe

Size

Size of Main

Repair ~~Renewal~~ — New Service

*am. 12-31-52*

Location

Date	Material	Amount	Total	Date	Amount
12/16/52	Labor	66 04		11-21-52	350 00
12/17/52	Labor	75 45		12-31-52	(40 88
	10% overhead	14 15	155 64		309 12
	120'-6" Sewer pipe @.342		41 04		
	1-6" 1/8 Bend		1 24		
	Joint Compound		7 20		
	10 Hr. Town Shovel @5.00		50 00		
	1/4 Hr. Trucking		3 00		
	Patching 17 x 9		51 00		
			309 12		
	<b>Labor</b>				
				7-21-53	Roots

