

Name Chester L. Blakely M.D.V.

Service No. 80

Address 509 Bedford Street

Location

Kind of Pipe

Size

Size of Main

Repair - ~~Renewal~~ - New Service

CON. 7-19-54

Location

Date	Material	Amount	Total	Date	Amount
6/2/54	Labor	67 67		5-21-54	Deposited 300 00
6/3/54	"	87 97	155 64	7-20-54	Refunded (22 87)
	10% overhead		15 56		277 13
	190' - 6" sewer pipe @ .3087		58 65		
	1 - 6" elbow		1 88		
	joint compound		11 40		
	5 hrs. town shovel @ 5.00		25 00		
	4 hrs. trucking @ .75		3 00		
	patching 6 x 3		6 00		
			277 13		
	Labor				

