

Name Leon Cormier & Sons, Inc.

Service No. 239

Address 21 Bellflower Street

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Location *Comm 2-8-60*

Date	Material	Amount	Total	Date	Amount
12-8-59	Labor	54.10		11-20-59	150.00
12-10-59	"	19.24	73.34	2-8-60	20.16
	10% O.H.	7.33	80.67	2-8-60	20.66
	60' 6" Transite pipe @.70		42.00	2-8-60	2.10
	23 1/2 ton 3/4" Stone @1.50		35.25		192.92
	4 hrs. Town Shovel @6.50		26.00		
	4 hrs. Trucking @.75		3.00		
	1 hr. Trucking @3.00		3.00		
	1 hr. Rogers Trailer @3.00		3.00		
			192.92		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....