

Name John Meurer

Service No.

81

Address 21 Bernard St.

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

CON. 7-13-53

Location

Date	Material	Amount	Total	Date	Amount
6/11/53	Labor	63 70		5-1-53	120 00
	10% overhead	6 37	70 07	7-13-53	(9 84)
	54'-6" Sewer pipe @ .342		18 47		115 16
	1-6" Elbow		1 88		
	Joint Compound		3 24		
	1 Hr. Town Shovel @5.00		20 00		
	2 Hr. Trucking		1 50		
			115 16		

Deposited
Refunded

Labor

