

Name Paul W. Olson

Service No. 8

Address 18 Bertwell Road

Lexington, Mass.

Location 18 Bertwell Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ - New Service

Com. 7-3-50

Location

Date	Material	Amount	Total	Date	Amount
May 3, '50	Labor	59 55	59 55	April 19 '50	175 00
	10% Overhead		5 96	May 20 '50	46 60
	70' - 6" Sewer Pipe @.28		19 60		128 31
	Joint Compound		4 20		
	Littlefield Shovel 4 1/2 hrs. @ 7.00		31 50		
	Hough Loader 2 hrs. @ 3.00		6 00		
	Trucking 2 hrs. @ .75		1 50		
			128 31		
	Labor				

