

Name **Harold W. Furness**

Service No. **39**

Address **39 Bertwell Road**

Lexington, Mass.

Location **39 Bertwell Road**

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ **New Service**

Com. **June 27, 1949**

Location

Date

Material

Amount

Total

Date

Amount

June 2, '49

Labor

31 60

31 60

May 31 '49
June 30 '49

Deputed
Refunded

75 00

10% Overhead

3 16

4 01

28' - 6" Sewer Pipe @.27

7 56

70 99

1 - 6" 1/8 Bend

1 49

Joint Compound

1 68

Littlefield Shovel 2 hrs. @ 7.00 14 00

Trucking 2 hrs. @.75

1 50

Patching 10 x 3

10 00

70 99

Labor

