

43447

Name Gilman Haven Service No. 32

Address 44 Bertwell Road

Lexington Location

Kind of Pipe COM. 6-16-52 Size Size of Main

~~Repair~~ New Service Location

Date	Material	Amount	Total	Date	Amount
5/2/52	Labor	37 01		4-8-52	Deposited 150 00
	10% overhead	3 70	40 71	6-16-52	Refunded (24 42)
	46' - 6" sewer pipe @ .342		15 73		125 58
	1 - 6" elbow		1 88		
	joint compound		2 76		
	7 hrs. Littlefield shovel		49 00		
	2 hrs. trucking		1 50		
	patching 14 x 3		14 00		
			<u>125 58</u>		
	Labor				

