

Name Roland Christenson

Service No. 17

Address 51 Bertwell Rd.

Location

Lexington

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

COM. 4-6-53

Location

Date	Material	Amount	Total	Date	Amount
3/20/53	Labor	53 80		3-5-53	200 00
	10% overhead	5 38	59 18	4-6-53	65 02
	62'-6" Sewer Pipe @.342		21 20		134 98
	10'-5" Transite Pipe @.55		5 50		
	1-6" Elbow		1 88		
	Joint Compound		3 72		
	6 Hrs. Littlefield Shovel @7.00		42 00		
	2 Hr. Trucking		1 50		
			134 98		
	Labor				

Deposited
Refunded

