

Name Robert Dean

Service No. 51

Address 55 Bertwell Road

Lexington

Location 55 Bertwell Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Com 11-6-50

Location

Date		Material	Amount		Total		Date		Amount	
Sept. 26	'50	Labor	31	21			July 21	'50	Deposited	125 00
		10% Overhead	3	12	34	33				10 63
		56' - 6" Sewer Pipe @ 28¢			15	68				114 37
		Joint Compound			3	36				
		8½ hrs. Littlefield Shovel			59	50				
		2 hrs. Trucking			1	50				
					114	37				
		Labor								

