

Name Henry E. Andrews

Service No. 13

Address 61 Bertwell Road

Lexington, Mass.

Location 61 Bertwell Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~New Service~~

Com. 8-16-48

Location

Date	Material	Amount	Total	Date	Amount
Jul. 16, '48	Labor	7 08		July 6 '48	200 00
17	"	71 43		July 20 '48	23 27
20	"	19 83	98 34		176 23
	10% Overhead		9 83		
	7 1/4' - 6" Sewer Pipe @.26		19 24		
	Joint Compound		4 44		
	Compressor 2 1/2 hrs. @ 1.75		4 38		
	Littlefield Shovel 5 1/2 hrs.		38 50		
	Trucking 2 hrs. @.75		1 50		
			176 23		
	Labor				

