

Name Ralph Carville

Service No. 95

Address 76 Bertwell Road

Lexington

Location 76 Bertwell Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ - New Service

Com. 3-6-50

Location

Date	Material	Amount	Total	Date	Amount
Jan. 30 '50	Labor	54 37		Dec. 27 '49	150 00
	10% Overhead	5 44	59 81	Mar 9 '50	32 85
	58' - 6" Sewer Pipe @.26		15 08		112 63
	1 - 6"-1/8 Bend		1 28		
	Joint Compound		3 48		
	4 1/2 hrs. Littlefield Shovel		31 50		
	2 hrs. Trucking		1 50		
			112 65		
				4/14/60	Roots & Grass
				11/6/67	Roots
	Labor			2/10/70	Roots 45' from trap
				10/14/71	Roots
					Letter 11/16/71

