

Name George Pumpelly

Service No. 116

Address 7 Berwick Road

Lexington, Mass.

Location 7 Berwick Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Location

| Date | Material | Amount | Total | Date | Amount |
|--------------|--------------------------------|--------|--------|-------------|--------|
| Oct. 22, '48 | Labor | 50 03 | | Sept 25 '48 | 150 00 |
| 23 | " | 54 96 | | Jan 29 '49 | 73 01 |
| 26 | " | 26 50 | | | 223 01 |
| 27 | " | 15 58 | 147 07 | | |
| | 10% Overhead | | 14 71 | | |
| | 1/2' - 6" Sewer Pipe @.26 | | 10 92 | | |
| | 20' - 1/4" Sewer Pipe @.50 | | 10 00 | | |
| | 1 - 6" Elbow | | 1 50 | | |
| | Joint Compound | | 3 52 | | |
| | Compressor 10 hrs. @ 1.75 | | 17 50 | | |
| | Trucking 2 hrs. @ .75 | | 1 50 | | |
| | Patching 15 x 3 | | 15 00 | | |
| | Labor Dynamite 3 lbs. @ .21 | | 63 | | |
| | Exploders 6 @ .LL | | .66 | | |
| | | | 223 01 | | |

