

Name Milton Shaw

Service No. 127

Address 8 Berwick Road

Location

Kind of Pipe COM. 8-31-53

Size

Size of Main

~~Repair~~ ~~Renewal~~ - New Service

Location

| Date | Material | Amount | Total | Date | Amount |
|---------|---------------------------------|--------|--------|---------|-----------------|
| 7/27/53 | Labor | 64 58 | | 6-22-53 | Deposited 175 - |
| | 10% overhead | 6 46 | 71 04 | 8-31-53 | Refunded 4 18 |
| | 58' - 5" transite pipe @ .55 | | 31 90 | | 170 82 |
| | 1 - 6" elbow | | 1 88 | | |
| | 7 hrs. Littlefield shovel @7.50 | | 52 50 | | |
| | 2 hrs. trucking @ .75 | | 1 50 | | |
| | patching 12 x 3 | | 12 00 | | |
| | | | 170 82 | | |
| | Labor | | | | |

