

Name Raymond W. James

Service No. 182

Address 66 Blake Rd.

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

COM. 11-23-53

Location

Date	Material	Amount	Total	Date	Amount
10/14/53	Labor	33 78		10-16-53	<i>Deputed 100 00</i>
	10% overhead	3 38	37 16	11-23-53	<i>Refunded (34 70)</i>
	32"-6" Sewer Pipe @ .3036		9 72		<i>65 30</i>
	Joint compound		1 92		
	2 Hr. Littlefield Shovel	7.50	15 00		
	2 Hr. Trucking		1 30		
			65 30		
	Labor				

