



Address	Map and Lot	Permit Number	Contractor Name	Inspector
2 Blossom St	9-16	5354	McLaughlin, James M. Inc.	Dpavlik
Date	Material	Depth of Cover	Amount	
9/1/2015	6"x6" PVC to AC Fernco	7 ft	1	
	6" PVC Pipe - SDR 35		38.75 ft	
	PVC Clean out and Fernco		1	
Type of work completed				

New 6" PVC sewer service installed to new house, connection to main.