



Address	Map and Lot	Permit Number	Contractor Name	Inspector
6 Blossom St	9-18	6217	Arlex Oil Corporation	msprague
Date	Material	Depth of Cover	Amount	
6/25/2015	6" Saddle Connection	7 ft	1-Connect to sewer main	
	6" PVC Pipe - SDR 35		68.5 ft	
	6" PVC Clean out		1	
	6" PVC Pipe - SDR 35		11.5 ft to HSE	
Type of work completed				
New 6" PVC sewer service installed to new house, connection to main.				