

Name **Harry Cataldo**

Service No. **124**

Address **59 Bow Street**

**Lexington, Mass.**

Location **59 Bow Street**

Kind of Pipe

Size

Size of Main

~~Repair~~ **New Service**

Com. **12-31-50**

Location

Date	Material	Amount	Total	Date	Amount
Nov. 14, '50	Labor	11 30		Nov 14 '50	100 00
Nov. 15, '50	Labor	<u>46 27</u>	57 57	Feb 21 '51	12 43
	10% Overhead		5 76		112 43
	40' - 6" Sewer Pipe		11 20		
	Joint Compound		2 40		
	Brox Shovel 3 hrs. @ 9.00		27 00	Bill sent 1-12-51	
	Trucking 2 hrs. @ .75		1 50		
	Patching 7 x 3		<u>7 00</u>		
			112 43		
	Labor				

