

Name Edward Tocio

Service No. 126

Address 62 Bow Street  
(21 Crescent Hill Ave.,)

Location

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service

Location

*Comm 12-4-61*

Date	Material	Amount	Total	Date		Amount
9/27/61	Labor	72 08		9-20-61	Deposit	250 00
	10% O.H.	7 21	79 29	12-4-61	Retund	<del>69 00</del>
	60' 6" Transite Pipe @ .78		46 80			180 99
	190° Transite Elbow		5 40			
	3 Hrs. Insley Shovel @ 6.50		19 50			
	1 Hr. Trojan Loader @ 3.00		3 00			
	2 Hrs. Trucking @ 3.00		6 00			
	21 X 3 Patch		21 00			
			180 99			

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**  
**SEWER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in ..... Street.      Work completed .....

Remarks: .....  
.....  
.....