

Name Mr. Mortensen

Service No. 101

Address 80 Bow Street

Location 80 Bow Street

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Com 11-6-50

Location

Date		Material	Amount	Total	Date	Amount
Oct. 83	'50	Labor	63 92		Oct 6 '50	125 00
		10% Overhead	6 39	69 31	Dec 5 '50	12 77
		44' - 6" Sewer Pipe		12 32		137 77
		Joint Compound		2 64		
		4 hrs. Brox Shovel		36 00		
		2 hrs. Trucking		1 50	Bill sent 11-15-50	
		Patching 15 x 3		15 00		
				137 77		
		Labor				

