

Name S. Santosusso

Service No. 66

Address 91 Bow Street

Lexington, Mass.

Location 91 Bow Street

Kind of Pipe

Size

Size of Main

~~REPAIR EXISTING~~ New Service

Com. 10-10-49

Location

Date	Material	Amount	Total	Date	Amount
Aug. 30, '49	Labor	30 91	30 91	Aug 31 '49	20 00
	10% Overhead		3 09	Oct 13 '49	10 53
	26' - 6" Sewer Pipe @.265		6 89		59 47
	1 - 6" Elbow		1 52		
	Joint Compound		1 56		
	Littlefield Shovel 2 hrs. @7.00		14 00		
	Trucking 2 hrs. @.75		1 50		
			59 47		
	Labor				

