

Name Chester Banks

Service No. 96

Address 8 Bowser Road

Lot #31

Sta. 3+91

El. 181.93

Location

Kind of Pipe

Size

Size of Main

~~REPAIR~~ RENEWAL - New Service

WO # 8096

Location

Comm 10-28-6

Date	Material	Amount	Total	Date	Amount
6-23-62	Labor	18.19		8-7-63	Deposit 200 00
	10% O.H.	1.82	20.01	10-28-63	Refund 87 91
	33' 6" Transite pipe @.78		25.74		112 09
	BILL WHEN CONNECTED		45.75		
8-14-63	Labor	21.12			
	10% O.H.	2.11	23.23	2-21-64	I.B. 32 06
	36' 6" Transite pipe @.82		29.52	2-24-64	I.B. 56 05
	1 11 1/2° Transite Bend		4.09		
	1 Hr. Town Shovel @6.50		6.50		
	1 Hr. Trucking @3.00		3.00		
2-24-64	Repair		112.09		
	13' 6" Transite				
	1 6" Adapter				

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**  
**SEWER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in ..... Street. Work completed .....

Remarks: .....  
.....  
.....