

Name Benjamin Gott

Service No. 63

Address 38 Brandon Street

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

COM. 7-28-52

Location

Date	Material	Amount	Total	Date	Amount
------	----------	--------	-------	------	--------

5/29/52

Labor

77 31

85 04

5-1-52 Deposited

125 -

10% overhead

7 73

7-28-52 Paid

(3 25

54' - 6" sewer pipe @ .342

18 47

128 25

joint compound

3 24

4 hrs. town shovel @ 5.00

20 00

2 hrs. trucking

1 50

128 25

Labor

