

Name Joseph Harrington

Service No. 180

Address 40 Brandon St.

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~XXXXXX~~ New Service

COM. 11-23-53

Location

Date	Material	Amount	Total	Date	Amount
11/2/53	Labor	58.33		10-6-53 Deposited	150.00
	10% overhead	5.83	64.16	11-23-53 <del>Refunded</del>	(91.57)
	1/2' -6" Sewer Pipe @.3036		12.75		118.43
	Joint Compound		2.52		
	5 Hr. Littlefield Shovel @7.50		37.50		
	2 Hr. Trucking		1.50		
			118.43		
	<b>Labor</b>				

