

Name Richard Hamilton

Service No. 68

Address 43 Brandon Street

Location

Kind of Pipe

Size

Size of Main

~~Repair/Replacement~~ New Service


Location *Comm 7-17-61*

Date	Material	Amount	Total	Date	Amount
6-12-61	Labor	62.30		<i>6-2-61</i>	<i>Deposit</i> 200 00
6-13-61	Labor	45.35	107.65	<i>7-17-61</i>	<i>Paid by WPC #76</i> 21 10
	10% O.H.	10.77	118.42		<u>221 10</u>
	52' 6" Transite pipe @.78		40.56		
	1 11 $\frac{1}{4}$ " Transite Bend		5.10		
	1 6" Duplex Adapter		1.62		
	1 6" 90° Transite Elbow		5.40		
	4 Hrs. Town Shovel @6.50		26.00		
	3 Hrs. Trucking @3.00		9.00		
	15 x 3 Patch		15.00		
			<u>221.10</u>		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:
.....
.....