

Name **Howard Storer**

Service No. **20 115**

Address **7 Brandon St., Lexington**

Location **Same**

Kind of Pipe

Size

Size of Main

~~Repair - General~~ **New Service**

Location

Date	Material	Amount	Total	Date	Amount
This service installed in 1934. No charge for connection with sewer this year.					
	Labor				

