



Address	Map and Lot	Permit Number	Contractor Name	Inspector
118 Burlington St	77-153	7049	Express Excavation	mweis
Date	Material	Depth of Cover	Amount	
12/1/2016	6" PVC Pipe - SDR 35		70 ft	
	6" Cleanout		1	
	6" 22 deg bend		2	
<b>Type of work completed</b>				
New 6" PVC sewer service connected near ROW				